### BOSLOWICK   FTC	Map reference  5W 79332 31315  5W 79593 31274  5W 79472 31839  5W 79420 31978  5W 79377 31962  5W 80074 31258  5W 79579 31832	Ownership CC CC CC CC CC ?	POS POS POS CC? swanpool	CC Now have plans for this site, tree planting, play area and formal pathways  Quite large grass area that would benefit from some areas of planting  Quite large grass area that would benefit from some areas of planting	Consider tree planting	Benches/Seating
## BOSLOWICK   FTC	Map reference  5W 79332 31315  5W 79593 31274  5W 79472 31839  5W 79420 31978  5W 79377 31962  5W 80074 31258  5W 79579 31832	Ownership CC CC CC CC CC CC	POS POS POS POS POS	Landscaping/Horticultural works  The entrance to Goldenbank could have some planting to add interest and add to amenity of the area  CC Now have plans for this site, tree planting, play area and formal pathways  Quite large grass area that would benefit from some areas of planting  Quite large grass area that would benefit from some areas of planting	Consider tree planting Consider tree planting Consider tree planting	Benches/Seating
FTC         Ref No.         Site name         M           001         POS Treveglos rd         SI           002         POS Penhale rd/Treveglos rd         SI           009         Prislow fields POS         SI           020         Verge Boslowick shops 1.         SI           021         Verge Boslowick shops 2.         SI           073         POS Rear of Swanpool car park         SI           093         Bosvale POS?         SI           094         Bosvale POS?         SI           095         Bosvale POS?         SI           096         Bosvale, Meadow Court         SI	5W 79332 31315 5W 79593 31274 5W 79472 31839 5W 79420 31978 5W 79377 31962 5W 80074 31258 5W 79579 31832	CC CC CC CC?	POS POS POS POS POS	The entrance to Goldenbank could have some planting to add interest and add to amenity of the area  CC Now have plans for this site, tree planting, play area and formal pathways  Quite large grass area that would benefit from some areas of planting  Quite large grass area that would benefit from some areas of planting	Consider tree planting Consider tree planting Consider tree planting	Benches/Seating
Ref No. Site name	5W 79332 31315 5W 79593 31274 5W 79472 31839 5W 79420 31978 5W 79377 31962 5W 80074 31258 5W 79579 31832	CC CC CC CC?	POS POS POS POS POS	The entrance to Goldenbank could have some planting to add interest and add to amenity of the area  CC Now have plans for this site, tree planting, play area and formal pathways  Quite large grass area that would benefit from some areas of planting  Quite large grass area that would benefit from some areas of planting	Consider tree planting Consider tree planting Consider tree planting	Benches/Seating
Ref No. Site name	5W 79332 31315 5W 79593 31274 5W 79472 31839 5W 79420 31978 5W 79377 31962 5W 80074 31258 5W 79579 31832	CC CC CC CC?	POS POS POS POS POS	The entrance to Goldenbank could have some planting to add interest and add to amenity of the area  CC Now have plans for this site, tree planting, play area and formal pathways  Quite large grass area that would benefit from some areas of planting  Quite large grass area that would benefit from some areas of planting	Consider tree planting Consider tree planting Consider tree planting	Benches/Seating
001 POS Treveglos rd SN 002 POS Penhale rd/Treveglos rd SN 009 Prislow fields POS SN 020 Verge Boslowick shops 1. SN 021 Verge Boslowick shops 2. SN 073 POS Rear of Swanpool car park SN 093 Bosvale POS? SN 094 Bosvale POS? SN 095 Bosvale POS? SN 096 Bosvale, Meadow Court SN	5W 79332 31315 5W 79593 31274 5W 79472 31839 5W 79420 31978 5W 79377 31962 5W 80074 31258 5W 79579 31832	CC CC?	POS POS POS	add to amenity of the area  CC Now have plans for this site, tree planting, play area and formal pathways  Quite large grass area that would benefit from some areas of planting  Quite large grass area that would benefit from some areas of planting	Consider tree planting Consider tree planting Consider tree planting	
009 Prislow fields POS SN 020 Verge Boslowick shops 1. SN 021 Verge Boslowick shops 2. SN 073 POS Rear of Swanpool car park SN 093 Bosvale POS? SN 094 Bosvale POS? SN 095 Bosvale POS? SN 096 Bosvale, Meadow Court SN	5W 79472 31839 5W 79420 31978 5W 79377 31962 5W 80074 31258 5W 79579 31832	CC CC?	POS POS POS	CC Now have plans for this site, tree planting, play area and formal pathways  Quite large grass area that would benefit from some areas of planting  Quite large grass area that would benefit from some areas of planting	Consider tree planting  Consider tree planting	
009 Prislow fields POS SN 020 Verge Boslowick shops 1. SN 021 Verge Boslowick shops 2. SN 073 POS Rear of Swanpool car park SN 093 Bosvale POS? SN 094 Bosvale POS? SN 095 Bosvale POS? SN 096 Bosvale, Meadow Court SN	5W 79472 31839 5W 79420 31978 5W 79377 31962 5W 80074 31258 5W 79579 31832	CC CC?	POS POS POS	CC Now have plans for this site, tree planting, play area and formal pathways  Quite large grass area that would benefit from some areas of planting  Quite large grass area that would benefit from some areas of planting	Consider tree planting  Consider tree planting	
020 Verge Boslowick shops 1. SN 021 Verge Boslowick shops 2. SN 073 POS Rear of Swanpool car park SN 093 Bosvale POS? SN 094 Bosvale POS? SN 095 Bosvale POS? SN 096 Bosvale, Meadow Court SN	5W 79420 31978 5W 79377 31962 5W 80074 31258 5W 79579 31832	CC CC?	POS	pathways  Quite large grass area that would benefit from some areas of planting  Quite large grass area that would benefit from some areas of planting	Consider tree planting	
021 Verge Boslowick shops 2. SN 073 POS Rear of Swanpool car park SN 093 Bosvale POS? SN 094 Bosvale POS? SN 095 Bosvale POS? SN 096 Bosvale, Meadow Court SN	5W 79377 31962 5W 80074 31258 5W 79579 31832	cc?	POS	Quite large grass area that would benefit from some areas of planting  Quite large grass area that would benefit from some areas of planting		
073 POS Rear of Swanpool car park SN 093 Bosvale POS? SN 094 Bosvale POS? SN 095 Bosvale POS? SN 096 Bosvale, Meadow Court SN	5W 80074 31258 5W 79579 31832	CC?			Consider tree planting	
093 Bosvale POS? SN 094 Bosvale POS? SN 095 Bosvale POS? SN 096 Bosvale, Meadow Court SN	SW 79579 31832		CC? swanpool			
094 Bosvale POS? S\ 095 Bosvale POS? S\ 096 Bosvale, Meadow Court S\	744 75575 51052	?	i	Unkempt grass area. Consider regular cutting	Consider tree planting	Consider picnic table
095 Bosvale POS? SI 096 Bosvale, Meadow Court SI	SW 79546 31839		Amenity woodland	Consider improvement as a properly managed woodland walk.		
096 Bosvale, Meadow Court SN		?	Amenity woodland	Consider improvement as a properly managed woodland walk.		
,	SW 79473 31855	?	Amenity woodland	Consider improvement as a properly managed woodland walk.		
101 Swanvale POS S\	SW 79647 31835	?	Amenity woodland	Could be included in the managed woodland walk ref:093,094,095		
	SW 79744 32061	СС	Amenity woodland	High ecological value, no manament plan currently in place for this area, needs to be improved through proper countryside management.		
104 Berryman cres POS (CHL)	SW 79703 31980	CHL	CHL POS	Grass area could be improved through shrub planting		
1206 Allotments. Bickland Water Road SV	SW 79193 31275	СС	Allotments			
TRESCOBEAS						
FTC						
Ref No. Site name N	Map reference	Ownership	Usage	Landscaping/Horticultural works	Tree Planting	Benches/Seating
123 Maytree old nursery site		СС	CC old	Could be improved as a picnic area, enhance the planting to increase horticulural interest		Big open grass bank, consider adding picn
140 POS (various)Longfield B. SN	SW 79448 32608	CC Adopted	CC Adopted various	Could carry out enhance planting for increased amenity, colour & horticultural interest		
146 POS (various)Longfield H. SN	SW 79141 32631	CC Adopted	CC Adopted various	Could carry out enhance planting for increased amenity, colour & horticultural interest est £4k		
201 Falmouth hospital OS Surrounding SN	SW 79666 32993	NHS		The hospital grounds could be a lot better through further planting of borders to give more colour and better maintenance regime.		
202 Falmouth hospital OS Surrounding SN	SW 79629 32923	NHS	NHS hospital	The hospital grounds could be a lot better through further planting of borders to give more colour and better maintenance regime.		
203 Falmouth hospital OS Surrounding SN	SW 79588 32954	NHS	NHS hospital	The hospital grounds could be a lot better through further planting of borders to give more colour and better maintenance regime.		
228 POS Conway rd SN	SW 78879 33061	СС	POS	Area of cut grass, used for nothing, consider adding a central shrub border		

236 OS Opposite cricket ground B. 238 CHL Wooded OS In front of Trecarne	SW 79127 33470	?	OS	Would benefit from a management plan and ongoing maintenance		
238 CHL Wooded US In front of Trecarne	SW 79342 33592	CHL	Woodland	This woodland area would be enhanced by adding a surfaced woodland		
				walk pathway, clearing away all dumped rubbish, clearance of		
				undergrowth and bulb planting. Put in place a woodland management		
				plan.		
239 Jewish cemetery	SW 79457 33860			Formalise access, with improved pathway and increased maintenance.		
				Project ongoing to repair headstones.		
240 Dissenters burial ground	SW 79463 33839		dissenters	Formalise access, with improved pathway and increased maintenance.		
				Project ongoing to repair headstones, boundary walls, access arch and		
				steps. Consider improving concrete structure to house FO group's tools.		
				FO have proposed area for interrment/scattering of cremated remains.		
				Additional land owned by Sainsbury could be included within the site.		
				Further vegetation clearance required and land managed as wild area.		
241 LPO Beside Dissenters burial ground	SW 79453 33790	Sainsburys	Sainsburys	See 240		
_			dissenters			
244 LPO Sainsbury embankment	SW 79504 33743	Sainsburys	OS	This site should be improved by Sainsbury as is not a credit to their		
				business		
247 CHLOS Beside Sub stn Ashfield rd	SW 79445 33672	CHL	CHL O/S	Consider screening sub station with tree planting .	Under-plant tree planting with a	
					shrub border	
248 CHLOS Entrance to Ashfield	SW 79595 33669	CHL	CHL O/S	Improve the hedge maintenance. Consider additional planting between		
				hedge and Hypericum		
249 CHLOS Entrance to Ashfield	SW 79606 33624	CHL	CHL O/S	Improve the hedge maintenance. Consider additional planting between		
				hedge and Hypericum		
250 CHLOS Ashfield rd next to no.1	SW 79550 33602	CHL	CHL O/S		Consider tree planting	
251 CHLOS Ashfield rd next to no.14	SW 79524 33586	CHL	CHL O/S		Consider tree planting	
252 CHLOS Porhan green in front of 1-5	SW 79535 33558	CHL	CHL O/S	Consider installing a shrub border to add colour/interest, as there's so		
_				much open grass area around this estate		
253 CHLOS Porhan green in front of 6-11	SW 79496 33583	CHL	CHL O/S	Big open grass bank, consider adding picnic tables and benches. Consider	Consider tree planting	Big open grass ban
				tree planting or adding a shrub border.		consider adding pio
254 CHLOS Porhan green in front of 12-13	SW 79478 33599	CHL	CHL O/S	Consider enhancing the boundary by including shrubs along the fenceline	Consider tree planting	
_				and tree planting.		
258 CHLOS Arundell gdns central OS	SW 79453 33521	CHL	CHL O/S	Carry out enkanced planting for increased amenity, colour and		
				horticultural interest		
259 CHLOS Karensa green beside 19&20	SW 79364 33492	CHL	CHL O/S		Consider tree planting	
260 CHLOS Karensa green central OS	SW 79352 33440	CHL	CHL O/S		Consider tree planting	Consider picnic
						benches and/or sea
261 CHLOS Trecarne	SW 79319 33539	CHL	CHL O/S	Consider naturalised bulb planting		
262 CHLOS Pengelly plc in front of 1-11	SW 79251 33428	CHL	CHL O/S	Improve hedge maintenance		
263 CHLOS Lowenack cl central OS	SW 79285 33353	CHL	CHL O/S		Consider further tree planting.	Consider picnic
						benches and/or sea
264 CHLOS Tuke cl central OS	SW 79391 33367	CHL	CHL O/S		Consider further tree planting	Consider picnic
204 CITLOS TUNE CI CEITH di OS	244 1232T 22201	CITE	CITE U/3		Consider further tree planting.	benches and/or sea
						benches and/or sea
265 CHLOS Noweth plc A.	SW 79391 33283	CHL	CHL O/S		Consider further tree planting.	Consider picnic
						benches and/or sea
					1	1
266 CHLOS Noweth plc B.	SW 79426 33305	CHL	CHL O/S		Consider further tree planting.	Consider picnic

267	CHLOS Noweth plc C.	SW 79448 33326	CHL	CHL O/S		Consider further tree planting.	Consider picnic benches and/or seating
							belienes unu/or seuting
271	CHLOS Hayman way beside 34-40	SW 79301 33256	CHL	CHL O/S	Consider central shrub border to add colour/interest		
FTC	PENWERRIS				 		
	Site name	Map reference	Ownership	Usage	Landscaping/Horticultural works	Tree Planting	Benches/Seating
			_				
	Land behind Old PO & Municipal	SW 80598 32909	?	O/S	Overgrown bank that could benefit from tidying up although gradient makes it unfit for much use.		
	building (wooded bank) The Beacon	SW 80313 33206	CHL	CHLOS	Could carry out enhanced planting for increased amenity, colour &		Consider further
203	The Beacon	300 00313 33200	CITE	CITEOS	horticultural interest.		facilities, such as picnic
						benches and bespoke	
							barbeque facilities
201	Land behind RCYC and beach	SW 80548 33283	2	0/5	Would hangfit from a management plan enhancement with improved		
291	Land Dening NCTC and Deach	3VV 0U340 33283	:	O/S	Would benefit from a management plan, enhancement with improved access and ongoing maintenance		
297	POS Penarth rd	SW 80192 33243	CHL	CHLOS	Consider installing a shrub border each side of central path to add		
					colour/interest, as there's so much open grass in this area.		
301	CHLOS Grenville cres	SW 79893 33216	CHL	CHLOS		Consider tree planting	
302	CHLOS Verges Grenville rd (from/to)	SW 79862 33179 to SW	CHL	CHLOS	Improve footpath maintenance. Trees require a weeded & mulched tree		
		80040 33449			pit and re-staking.		
303	CHLOS Robert Hitchins rd	SW 80058 33309	CHL	CHLOS		Plant tree, one removed has not	
204	CIU OC Dahara Hillahi arad	CVAV 000CO 22202	CIII	CI II OS		been replaced	
304	CHLOS Robert Hitchins rd	SW 80060 33293	CHL	CHLOS	2 youngish established trees consider under-planting with naturalised bulbs		
305	CHLOS Robert Hitchins rd	SW 80097 33314	CHL	CHLOS		Plant a further tree	
306	CHLOS Robert Hitchins rd		CHL	CHLOS		Plant another tree symetrical to	
						the existing one.	
307	CHLOS Robert Hitchins rd	SW 80126 33294	CHL	CHLOS		Plant another tree symetrical to	
						the existing one.	
308	CHLOS Robert Hitchins rd	SW 80129 33317	CHL	CHLOS		Plant another tree symetrical to	
200	CILLOC Dala and Historian and	CVV 00400 22242	CIII	CHIOC		the existing one.	
309	CHLOS Robert Hitchins rd	SW 80109 33342	CHL	CHLOS		4 grass areas, one has a tree, plant a tree centrally in the	
						other 3	
310	CHLOS Robert Hitchins rd	SW 80187 33313	CHL	CHLOS		Consider a further 2 trees in line	
						with the existing one	
	CHLOS Robert Hitchins rd		CHL	CHLOS	Form weeded & mulched treepit around existing Cherry		
	CHLOS Robert Hitchins rd		CHL	CHLOS	Form weeded & mulched treepit around existing Cherry		
313	CHLOS Robert Hitchins rd	SW 80231 33368	CHL	CHLOS		Replace snapped fastigiate Oak,	
						weeded & mulched tree pit	
24.1	CILLOC Old Hill area (for or he)	CM 70007 22 472 L C C C	CIII	CITI OC		stake etc.	
314	CHLOS Old Hill cres (from/to)	SW 79997 33472 to SW 79861 33566	CHL	CHLOS		Remove/replace dead tree near bench. Plant tree on bank	
		79861 33566				between no's. 28-30.	
	ARWENACK		1		'	122330000000000000000000000000000000000	
FTC	ANVENACE						
	Site name	Map reference	Ownership	Usage	Landscaping/Horticultural works	Tree Planting	Benches/Seating
		·	•		, <i>u</i> ,		
344	Arwenack st Rose gdn	SW 81261 32341	CC	Public garden			Consider seating/picnic bench facilities
							hanch tacilities

	Boscawen fields (picnic & POSs)	SW 80508 31466	СС	POS	Incorporate wild flower areas		Consider seating/picnic bench facilities
350	Boscawen fields (Dog walking)	SW 80602 31412	СС	POS	Incorporate wild flower areas	Consider tree planting	Consider seating/picnic bench facilities
351	Boscawen fields (Dog walking)	SW 80461 31338	СС	POS	Incorporate wild flower areas	Consider tree planting	Consider seating/picnic bench facilities
352	Boscawen fields (Lendien rocks)	SW 80597 31374	Private	POS	Tidy area and grass over.		
353	Falmouth Cemetery Lawn	SW 80233 31880	FTC	Open burial ground	Upgrade surfacing. Plant up border boundary with Ferndale rd. Tidy up dumped spoil and tidy/plant boundary with Swanpool hill.		
354	Falmouth Cemetery(FTC) Upper Old	SW 80354 31667	FTC	Closed cemetery		Further specimen tree planting	
355	Falmouth Cemetery(FTC) Lower Old	SW 80234 31721	FTC	Closed		Further specimen tree planting	
357	POS Grovehill cres	SW 81021 32292	СС	POS	Tidy & enhance existing planting		Improve seating
368	CHLOS and play area behind 30-41 Marlborough Ave	SW 80012 31990	CHL	Play area & CHLOS	, 5.	Consider tree planting	
369	CHLOS Marlborough Ave various verges	SW 79932 31987 to SW 80082 32080	CHL	CHLOS		Plant new trees in roadside	
	SMITHICK	<u>'</u>					<u>'</u>
FTC							
	. Site name	Map reference	Ownership	Usage	Landscaping/Horticultural works	Tree Planting	Benches/Seating
Ref No.	POS Gyllyng st	Map reference SW 80850 32654	Ownership CC	Usage POS	Clear overgrown rear bounday and replace with shrub/herbaceous border.	Tree Planting	Benches/Seating
1002		SW 80850 32654	·		Clear overgrown rear bounday and replace with shrub/herbaceous	Tree Planting	Benches/Seating
1002 419	POS Gyllyng st  POS Vernon plc next to Jewish synago	SW 80850 32654	СС	POS	Clear overgrown rear bounday and replace with shrub/herbaceous border.	Tree Planting	Benches/Seating
1002 419 420	POS Gyllyng st POS Vernon plc next to Jewish synago	SW 80850 32654 SW 80813 32722	СС	POS POS	Clear overgrown rear bounday and replace with shrub/herbaceous border.  Enhance through naturalisation of bulbs or consider as wild flower area  Cut and treat growth in walls, increase maintenance standard	Tree Planting	Benches/Seating
1002 419 420 421	POS Gyllyng st POS Vernon plc next to Jewish synagog POS Vernon plc, side of Jewish synagogue	SW 80850 32654 g SW 80813 32722 SW 80804 32770	cc cc cc	POS POS POS	Clear overgrown rear bounday and replace with shrub/herbaceous border.  Enhance through naturalisation of bulbs or consider as wild flower area  Cut and treat growth in walls, increase maintenance standard  Enhance through naturalisation of bulbs	Tree Planting	Benches/Seating
1002 419 420 421 422	POS Gyllyng st  POS Vernon plc next to Jewish synagog  POS Vernon plc, side of Jewish synagogue POS Vernon plc  POS Vernon plc POS below Smithick hill POS Opp Lawn Steps above Well Lane	SW 80850 32654 SW 80813 32722 SW 80804 32770 SW 80795 32788 SW 80840 32784	cc cc	POS POS POS	Clear overgrown rear bounday and replace with shrub/herbaceous border.  Enhance through naturalisation of bulbs or consider as wild flower area  Cut and treat growth in walls, increase maintenance standard	Tree Planting  Specimen tree planting.	Benches/Seating
1002 419 420 421 422 424	POS Gyllyng st  POS Vernon plc next to Jewish synagog  POS Vernon plc, side of Jewish synagogue  POS Vernon plc  POS Vernon plc	SW 80850 32654 SW 80813 32722 SW 80804 32770 SW 80795 32788 SW 80840 32784	cc cc cc	POS POS POS POS POS	Clear overgrown rear bounday and replace with shrub/herbaceous border.  Enhance through naturalisation of bulbs or consider as wild flower area  Cut and treat growth in walls, increase maintenance standard  Enhance through naturalisation of bulbs  Overgrown area, needs clearance and landscaping as garden		Benches/Seating
419 420 421 422 424 425	POS Gyllyng st  POS Vernon plc next to Jewish synagog  POS Vernon plc, side of Jewish synagogue POS Vernon plc  POS Vernon plc POS below Smithick hill POS Opp Lawn Steps above Well Lane Car Park	SW 80850 32654  SW 80813 32722  SW 80804 32770  SW 80795 32788  SW 80840 32784  SW 80849 32718	cc cc cc cc cc	POS POS POS POS POS POS POS	Clear overgrown rear bounday and replace with shrub/herbaceous border.  Enhance through naturalisation of bulbs or consider as wild flower area  Cut and treat growth in walls, increase maintenance standard  Enhance through naturalisation of bulbs  Overgrown area, needs clearance and landscaping as garden  Formalise footpath and clearance of bramble etc.  Overgrown area, although there are massive high drops that require	Specimen tree planting.  Additional specimen tree	Benches/Seating
419 420 421 422 424 425 440	POS Gyllyng st  POS Vernon plc next to Jewish synagogo POS Vernon plc, side of Jewish synagogue POS Vernon plc POS Vernon plc POS below Smithick hill POS Opp Lawn Steps above Well Lane Car Park POS below 1-6 Gyllyng St	SW 80850 32654  SW 80813 32722  SW 80804 32770  SW 80795 32788 SW 80840 32784 SW 80849 32718  SW 80879 32676  SW 80062 32146	CC CC CC CC CC CC CC	POS POS POS POS POS POS POS	Clear overgrown rear bounday and replace with shrub/herbaceous border.  Enhance through naturalisation of bulbs or consider as wild flower area  Cut and treat growth in walls, increase maintenance standard  Enhance through naturalisation of bulbs  Overgrown area, needs clearance and landscaping as garden  Formalise footpath and clearance of bramble etc.  Overgrown area, although there are massive high drops that require	Specimen tree planting.	Benches/Seating
419 420 421 422 424 425 440 441	POS Gyllyng st  POS Vernon plc next to Jewish synagogo POS Vernon plc, side of Jewish synagogue POS Vernon plc POS Vernon plc POS below Smithick hill POS Opp Lawn Steps above Well Lane Car Park POS below 1-6 Gyllyng St  CHLOS Marlborough grove	SW 80850 32654  SW 80813 32722  SW 80804 32770  SW 80795 32788 SW 80840 32784 SW 80849 32718  SW 80879 32676  SW 80062 32146	CC CC CC CC CC CC CC CC CC	POS POS POS POS POS POS CHLOS	Clear overgrown rear bounday and replace with shrub/herbaceous border.  Enhance through naturalisation of bulbs or consider as wild flower area  Cut and treat growth in walls, increase maintenance standard  Enhance through naturalisation of bulbs  Overgrown area, needs clearance and landscaping as garden  Formalise footpath and clearance of bramble etc.  Overgrown area, although there are massive high drops that require	Specimen tree planting.  Additional specimen tree planting	Benches/Seating
419 420 421 422 424 425 440 441	POS Vernon plc next to Jewish synagogo POS Vernon plc, side of Jewish synagogue POS Vernon plc POS Vernon plc POS below Smithick hill POS Opp Lawn Steps above Well Lane Car Park POS below 1-6 Gyllyng St CHLOS Marlborough grove CHLOS Marlborough grove in front 6,7	SW 80850 32654  SW 80850 32654  SW 80813 32722  SW 80804 32770  SW 80795 32788 SW 80840 32784 SW 80849 32718  SW 80879 32676  SW 80062 32146  SW 80034 32186 SW 79981 32237 SW 80915 32500	CC CC CC CC CC CC CC CC CC	POS POS POS POS POS POS CHLOS	Clear overgrown rear bounday and replace with shrub/herbaceous border.  Enhance through naturalisation of bulbs or consider as wild flower area  Cut and treat growth in walls, increase maintenance standard  Enhance through naturalisation of bulbs  Overgrown area, needs clearance and landscaping as garden  Formalise footpath and clearance of bramble etc.  Overgrown area, although there are massive high drops that require protection before further use is identified.	Specimen tree planting.  Additional specimen tree planting	Benches/Seating
419 420 421 422 424 425 440 441 441	POS Vernon plc next to Jewish synagogo POS Vernon plc, side of Jewish synagogue POS Vernon plc POS Vernon plc POS Vernon plc POS below Smithick hill POS Opp Lawn Steps above Well Lane Car Park POS below 1-6 Gyllyng St CHLOS Marlborough grove CHLOS Marlborough grove in front 6,72 CHLOS Margaret plc Woodehouse terrace allotments (FTC)	SW 80850 32654  SW 80850 32654  SW 80813 32722  SW 80804 32770  SW 80795 32788 SW 80840 32784 SW 80849 32718  SW 80879 32676  SW 80062 32146  SW 80034 32186 SW 79981 32237 SW 80915 32500  SW 80896 32527	CC CC CC CC CC CC CC CC CC	POS POS POS POS POS POS CHLOS CHLOS	Clear overgrown rear bounday and replace with shrub/herbaceous border.  Enhance through naturalisation of bulbs or consider as wild flower area  Cut and treat growth in walls, increase maintenance standard  Enhance through naturalisation of bulbs  Overgrown area, needs clearance and landscaping as garden  Formalise footpath and clearance of bramble etc.  Overgrown area, although there are massive high drops that require protection before further use is identified.	Specimen tree planting.  Additional specimen tree planting	Benches/Seating
419 420 421 422 424 425 440 441 442 452	POS Vernon plc next to Jewish synagogo POS Vernon plc, side of Jewish synagogue POS Vernon plc POS Vernon plc POS Vernon plc POS below Smithick hill POS Opp Lawn Steps above Well Lane Car Park POS below 1-6 Gyllyng St CHLOS Marlborough grove CHLOS Marlborough grove in front 6,7 CHLOS Margaret plc Woodehouse terrace allotments (FTC)	SW 80850 32654  SW 80850 32654  SW 80813 32722  SW 80804 32770  SW 80795 32788 SW 80840 32784 SW 80849 32718  SW 80879 32676  SW 80062 32146  SW 80034 32186 SW 79981 32237 SW 80915 32500  SW 80896 32527  SW 80873 32567	CC	POS POS POS POS POS POS CHLOS CHLOS Allotments	Clear overgrown rear bounday and replace with shrub/herbaceous border.  Enhance through naturalisation of bulbs or consider as wild flower area  Cut and treat growth in walls, increase maintenance standard  Enhance through naturalisation of bulbs  Overgrown area, needs clearance and landscaping as garden  Formalise footpath and clearance of bramble etc.  Overgrown area, although there are massive high drops that require protection before further use is identified.  Naturalise bulbs around base of trees  Reduce & shape hedges	Specimen tree planting.  Additional specimen tree planting	Benches/Seating